

Standard Tell-Tale

Standard Tell-Tale

Fixing Instructions

Mobile CAD Surveying Ltd

sales@mobilecadsurveying.co.uk

+44 (0) 844 567 2609

Fixing Instructions

1. Use screws or adhesive to fix
2. Fix the Tell-Tale over the crack with the vertical 0 line on the calibration scale parallel with the crack to be monitored
3. Ensure the numbers are the correct way up.
4. Cut the transparent tape with a sharp knife
5. If the crack opens or closes the cursor moves relative to the calibration scale. The opening or closing of the crack can then be recorded on the record sheet overleaf.

